



ARKANSAS ELITE WELDING ACADEMY

WELDING COMPETITION

Arkansas Elite Welding Academy, LLC
333 Rosebud Rd. Quitman, AR 72131
Phone: 833-ELITE-10

STEPS TO GETTING SIGNED UP!

1. Go Online to [Click Link to Welding Competition](#), Click Register and Choose a Time Slot to be Entered Into.

INSTRUCTIONS ON THE DAY OF COMPETITION!

1. Show Up Onsite and Enter Into the Main Building Entrance 30 Minutes Before Your Chosen Time Slot.
2. See Kelly Patrick at the AEWA Sign In Desk to Complete All Paper Work, Sign Waivers and Release Forms. (Competitors Under the Age of 18 Must be Accompanied by a Parent or Guardian.)
3. See an Instructor at the AEWA Table to Acquire Test Coupon and Competitor I.D. Number.
4. Put All Equipment Tools, Hood, Test Coupon, Etc. Into Designated Booth. (Make Sure Competitor is Wearing All Required PPE) Listed On Back.
5. Competitor Can Borrow Any Needed PPE or Tools From the AEWA Tool Room.
6. A Safety Meeting Will Be Held Before the Start of Each Competition.
7. Competitor May Utilize the Help of An Instructor to Set Machine and Amperage Ranges on the Back Side of Test Coupon.
8. Once Weld is Complete Competitor Shall Leave Test Coupon in Place and Report to an Instructor. (Instructor Will Take Completed Coupon to a Preliminary Judging Station / Do Not Leave Until Instructor Gives You the All Clear.) (The Top 5 Competitors From Each Wave Will be Listed on the Live Leader Board)
9. Once Instructor has Taken the Weld Test Coupon, Competitor Shall Clean Booth, Sweeping Up Rod Stubs, Slag and/or Other Debris.
10. Return Any Borrowed Tools and/or PPE to the AEWA Tool Room.
11. See Austin Harp at the AEWA Table to Receive Participation Scholarship and Prize Pack. (At this Time Competitor May Ask Any Questions He/She May Have Pertaining to Enrollment, Financial Options, Housing, Etc.)
12. Competition Leaders Should Plan to Return at 2:00 for the Awards Ceremony.