STRUCTURAL COUPON

MATERIALS

3/8" X 6" X 6" Flat Bar 1/4" X 4" X 4" Flat Bar 3/32" E7018 SMAW Electrodes

INSTRUCTIONS

2 Weld Passes on each side

1st Pass/Root on each side - 3/32" E7018

2nd Pass/Cap on each side - 3/32" E7018

Vertical Uphill Progression (Weld 2 & 3)

Weld made in either direction (Weld 1 & 4)

Cap Pass should be a 5/16" Fillet Weld

Weld each side in sequence from bottom to top

WELD 1: OVERHEAD 4F WELD 2: VERTICAL 3F

WELD 3: VERTICAL 3F

WELD 4: HORIZONTAL 2F

Weld all the way out. Staggered welds are for reference only.

2025 WELDING COMPETITION FOR HIGH SCHOOL SENIORS

